


G-ZERO Lathe

Power Tips




Roughing

The most common Source programming format for a lathe roughing operation is:



To rough and then take several clean up passes:



The **Rough** command is always programmed in pairs. The second **Rough** command must be identical to the first **Rough** command (of the pair).

Comp thru **Uncomp** describes the finished part geometry without lead-on or lead-off **Points**.


Optional:

Program a lead-on (approach) **Point** before the first **Rough** command. Program a lead-off (retract) **Point** after the second **Rough** command (of the pair).

OD


ID

OD ROUGHING (G71)




Tool **OD (in/out 2)**
 Comp **Cutter on the RIGHT**
 Program the contour towards the chuck.

ID ROUGHING (G71)




Tool **ID (in/out 1)**
 Comp **Cutter on the LEFT**
 Program the contour towards the chuck.

OD FACE ROUGHING (G72)




Tool **OD (in/out 2)**
 Comp **Cutter on the LEFT**
 Program contour away from the chuck.

ID FACE ROUGHING (G72)




Tool **ID (in/out 1)**
 Comp **Cutter on the RIGHT**
 Program contour away from the chuck.

◆ OD BACK GROOVING (G72)




Tool **OD (in/out 4)**
 Rough **Negative (-) zstock**
 Comp **Cutter on the RIGHT**
 Program contour towards the chuck.
 (Not available for Apprentice)

◆ ID BACK GROOVING (G72)




Tool **ID (in/out 3)**
 Rough **Negative (-) zstock**
 Comp **Cutter on the LEFT**
 Program contour towards the chuck.
 (Not available for Apprentice)

◆ OD BACK TURNING (G71)



Tool **OD (in/out 4)**
 Rough **Negative (-) zstock** **SAFEANG must be correct**
 Comp **Cutter on the LEFT**
 Program contour away from the chuck

◆ ID BACK TURNING (G71)



Tool **ID (in/out 3)**
 Rough **Negative (-) zstock** **Negative (-) depth of cut**
 SAFEANG must be correct
 Comp **Cutter on the RIGHT**
 Program contour away from the chuck

◆ ROUGHING UNDERCUTS

(Not available in Apprentice version)


OD DOUBLE UNDERCUT EXAMPLE:

Tool 1 in/out 2
Rough Negative (-) depth of cut
 Safeangle **MUST** be correct
Comp Cutter on the right
 Program contour towards the chuck.
Tool 2 in/out 4

Rough Negative (-) depth of cut
 Negative (-) z-stock
 Safeangle **MUST** be correct
Comp Cutter on the left
 Program contour away from the chuck.



Tool 1



Tool 1 and Tool 2

◆ ROUGHING CASTINGS

(Not available in Apprentice version)

If Comp - Uncomp (the final contour) will be programmed towards the chuck:


Program casting Points away from the chuck immediately after the **FIRST** Rough command before the contour.

If Comp - Uncomp (the final contour) will be programmed away from the chuck :

Program the casting Points towards the chuck immediately after the **FIRST** Rough command before the contour.


- 1 Tool
 - 2 Type
 - 3 Point (Approach Point if ID)
 - 4 Rough
 - 5 Point #1
 - 6 Point #2
 - 7 Point #3
 - 8 Point #4
 - 9 Comp
 - 10
 - 11
 - 12
 - 13 Uncomp
 - 14 Rough
- (Always program the casting **Points** before the part contour and always in the opposite direction.)
- (final contour)

OD CASTING





Rough Negative (-) depth of cut
 Safeangle **MUST** be zero (0).

ID CASTING



Rough Negative (-) depth of cut
 Safeangle **MUST** be zero (0).

◆ CALCULATING SAFE ANGLES (Not available in Apprentice version)


OD SAFE ANGLES	ID SAFE ANGLES
	
<p>OD Safe Angle = $(A - \text{clearance angle}) + 180^\circ$</p> <p><i>Ex:</i> $A = 45^\circ$ minimum desired clearance angle = 5° So, OD Safe Angle = $(45-5) + 180^\circ = 220^\circ$</p>	<p>ID Safe Angle = $180^\circ - (A - \text{clearance angle})$</p> <p><i>Ex:</i> $A = 45^\circ$ minimum desired clearance angle = 5° So, ID Safe Angle = $180^\circ - (45-5) = 140^\circ$</p>

Pipe Threading

(Reading your blueprint)


Major and minor OD as the thread ends:

PIPE ret0 tpf.75 x2.2 z-3
 THREAD maj2.2 tpi8 min2.1 S300 z.2 zfin-3 num5 a60




Major and minor OD at start point:

PIPE ret0 tpf.75 x1.7 z0
 THREAD maj1.7 tpi8 min1.6 S300 z.2 zfin-3 num5 a60




Major and minor OD slightly past the thread ends:

PIPE ret0 tpf.75 x2.2 z-3
 THREAD maj2.2 tpi8 min2.1 S300 z.2 zfin-3.2 num5 a60



Major and minor OD inside the thread:

Incremental values
 PIPE ret0 tpf.75 x1.85 z-1.5
 THREAD maj.05 tpi8 min-.05 S300 z.2 zfin-3 num5 a60



● Blueprint reference point

